



SKODA

SKODA

 Code 

**0-9**

135/8 ..... 1448

136 L ..... 1448

**A**

ADR ..... 1460

AEE ..... 1454

AEF ..... 1462

AEG ..... 1474

AEH ..... 1454

AEY ..... 1462

AGN ..... 1460

AGP ..... 1464

AGR ..... 1466

AGU ..... 1462

AHF ..... 1468

AKL ..... 1454

ALH ..... 1468

AME ..... 1450

AMF ..... 1450

AMX ..... 1482

APK ..... 1474

AQM ..... 1470

AQV ..... 1446

AQW ..... 1450

AQY ..... 1474

ARV ..... 1446

ARX ..... 1462

ARZ ..... 1462

ASV ..... 1470

ASY ..... 1470

ASZ ..... 1472

ATD ..... 1472



ATZ ..... 1450

AUA ..... 1450

AUB ..... 1450

AUM ..... 1462

AUQ ..... 1462

 Code 

AVB ..... 1472

AVF ..... 1472

AVU ..... 1454

AWT ..... 1462

AWX ..... 1472

AWY ..... 1446-1448

AXP ..... 1450

AXR ..... 1472

AYM ..... 1482

AZE ..... 1450

AZF ..... 1450

AZH ..... 1474

AZJ ..... 1474

AZL ..... 1474

AZM ..... 1476

AZQ ..... 1448

AZV ..... 1476

**B**

BBG ..... 1482

BBM ..... 1448

BBY ..... 1450

BBZ ..... 1450

BCA ..... 1450

BDG ..... 1482

BFQ ..... 1454

BGU ..... 1456

BJB ..... 1472

BKC ..... 1472

BKD ..... 1476

BKY ..... 1450

BLF ..... 1456

BLR ..... 1476



BLS ..... 1474

BLT ..... 1472

BLX ..... 1476

BLY ..... 1476

BMD ..... 1446-1448

 Code 

BME ..... 1448

BMM ..... 1476

BMN ..... 1478

BMP ..... 1476

BMS ..... 1452

BNM ..... 1452

BNV ..... 1452

BPZ ..... 1472

BSE ..... 1456

BSF ..... 1456

BSS ..... 1478

BSV ..... 1472

BSW ..... 1472

BTS ..... 1456

BUD ..... 1452

BVX ..... 1476

BVY ..... 1476

BVZ ..... 1476

BWA ..... 1478

BWW ..... 1478

BXE ..... 1472

BXW ..... 1452

BZB ..... 1462

BZG ..... 1448

**C**

CAVE ..... 1452

CAXA ..... 1452

CAXC ..... 1452

CAYA ..... 1456

CAYB ..... 1456

CAYC ..... 1456-1458

CBBB ..... 1478



CBDB ..... 1478

CBZA ..... 1448

CBZB ..... 1448

CCSA ..... 1458

CCZA ..... 1480

 Code 

CDA A ..... 1462

CDAB ..... 1462

CDE ..... 1458

CDF ..... 1458

CDVA ..... 1482

CEGA ..... 1478

CEVA ..... 1448

CFB ..... 1452

CFFB ..... 1480

CFGB ..... 1480

CFHA ..... 1480

CFHC ..... 1480

CFHF ..... 1480

CFJA ..... 1480

CFNA ..... 1458

CFWA ..... 1448

CGGA ..... 1454

CGM ..... 1480

CGPA ..... 1448

CGPB ..... 1448

CGZ ..... 1480

CHFA ..... 1448

CHGA ..... 1458

CHPA ..... 1454

CHTA ..... 1448

CHYA ..... 1446

CHYB ..... 1446

CLCA ..... 1480

CLCB ..... 1480

CLHA ..... 1460

CLHB ..... 1460

CLJA ..... 1480

CLSA ..... 1460

CMXA ..... 1458

CPGA ..... 1446

CRKB ..... 1460

CTHE ..... 1452

 Code 

 Code 

 Code 

 Code 

SKODA						
Ltr.						
1,0 AQV ARV	37 kW (50 PS)	FABIA	12/99-08/02	<b>02-36085-01</b> ⑫ <b>08-36087-01</b> ⑬	<b>61-36085-00</b> 047 103 383 B 73,5 Ø	<b>14-32167-01</b> N 907 957 01 (5x) +N 907 958 01 (4x) +N 907 956 01 (1x)
1,0 CHYA CHYB	44-55 kW (60-75 PS)	CITIGO	10/11→	<b>01-37675-01</b> ⑫ ⑬ ⑳ <del>02-37675-01</del> ⑫	<b>61-37675-00</b> 04C 103 383 H 75,5 Ø MLS	<b>14-32385-02</b> WHT 004 926 (8x)
1,0 CPGA	50 kW (68 PS)	CITIGO	11/12→	<b>01-37835-01</b> ⑫ ⑬ ⑳ <del>02-37835-01</del> ⑫	<b>61-37835-00</b> 04C 103 383 N 75,5 Ø MLS	<b>14-32385-02</b> WHT 004 926 (8x)
1,2 AWY BMD	40 kW (54 PS)	FABIA	→6Y 5 280 000 07/01-03/08	<b>02-36050-01</b> ⑫ <b>08-36942-01</b> ⑬	<b>61-36050-00</b> 03D 103 383 G 77 Ø 0,6 mm MLS	<b>14-32123-02</b> WHT 001 808 (8x)

<b>71-36056-00</b> 047 103 483	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	<b>71-36084-00</b> 047 129 717 B	2x	<b>71-36086-00</b> 047 253 050 <b>71-36723-00</b> R 047 253 039 H <b>71-36724-00</b> L 047 253 039 J	<b>71-36087-00</b> 047 103 609 B
<b>81-36787-00</b> K ← 047 103 085 42x58x8 A SL RD FPM <b>81-36788-00</b> K → 047 103 085 A 85x105x12 A SL LD FPM	<b>71-39983-00</b> 04C 103 483 B ① →04/13	<b>12-42741-02</b> 04E 109 675 (6x) +04E 109 675 A (6x) <b>70-42741-00</b> ES 6x 04E 109 675 <b>70-42742-00</b> AS 6x 04E 109 675 A	<b>41-77647-00</b> 04C 129 717 B	<b>71-10021-00</b> 1S0 253 115 B	<b>70-31414-10</b>
<b>81-42697-00</b> K ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>81-42736-00</b> N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>81-42734-00</b> N → 04E 103 085 24x39x8 A SL LD PTFE ACM	<b>71-39983-10</b> 04C 103 483 E ① 05/13→	<b>12-42742-01</b> 04E 109 675 A (12x) <b>70-42742-00</b> 04E 109 675 A	12x	<b>41-77647-00</b> 04C 129 717 B	<b>71-10021-00</b> 1S0 253 115 B
<b>81-42697-00</b> K ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>81-42736-00</b> N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>81-42734-00</b> N → 04E 103 085 24x39x8 A SL LD PTFE ACM	<b>71-39983-00</b> 04C 103 483 B ① →04/13	<b>12-42742-01</b> 04E 109 675 A (12x) <b>70-42742-00</b> 04E 109 675 A	12x	<b>41-77647-00</b> 04C 129 717 B	<b>71-10021-00</b> 1S0 253 115 B
<b>81-42697-00</b> K ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>81-42736-00</b> N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>81-42734-00</b> N → 04E 103 085 24x39x8 A SL LD PTFE ACM	<b>70-31414-10</b>	<b>71-39983-10</b> 04C 103 483 E ① 05/13→	<b>71-39983-10</b> 04C 103 483 E ① 05/13→	<b>41-77647-00</b> 04C 129 717 B	<b>71-10021-00</b> 1S0 253 115 B
<b>81-42697-00</b> K ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>81-42736-00</b> N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>81-42734-00</b> N → 04E 103 085 24x39x8 A SL LD PTFE ACM	<b>70-31414-10</b>	<b>70-31414-10</b>	<b>70-31414-10</b>	<b>71-36066-00</b> 03D 129 717 A	<b>71-36101-00</b> 03D 253 039 B
<b>81-34366-00</b> K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-34819-00</b> K → 021 103 051 C 85x105x11 A SL LD PTFE ACM	<b>70-31414-10</b>	<b>70-31414-10</b>	<b>70-31414-10</b>	<b>70-31414-10</b>	<b>70-31414-10</b>

⑳ ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач

AS Auslaßseite / exhaust side / côté échappement / lado de escape / lato scarico / сторона выпуска  
ES Einlaßseite / intake side / côté admission / lado de admisión / lato aspirazione / сторона впуска



SKODA						
Ltr.						
1,2 AWY BMD	40 kW (54 PS)	FABIA	6Y 5 280 001 → 07/01-03/08	<b>02-36050-01</b> <sup>12</sup> <b>08-36942-01</b> <sup>13</sup>	<b>61-36050-00</b> 03D 103 383 G 77 Ø 0,6 mm MLS 	<b>14-32123-02</b> WHT 001 808 (8x) 
1,2 AZQ BME BZG CEVA CGPA CGPB CHTA	44-51 kW (60-70 PS)	FABIA ROOMSTER	01/03 →	<b>02-36045-01</b> <sup>12</sup> <b>08-36942-01</b> <sup>13</sup>	<b>61-36045-00</b> 03E 103 383 F 77 Ø 0,9 mm MLS 	<b>14-32120-02</b> 036 103 384 B (8x) 
1,2 BBM CHFA	44 kW (60 PS)	FABIA	12/06 →	<b>02-36050-01</b> <sup>12</sup> <b>08-36942-01</b> <sup>13</sup>	<b>61-36050-00</b> 03D 103 383 G 77 Ø 0,6 mm MLS 	<b>14-32123-02</b> WHT 001 808 (8x) 
1,2 CBZA CBZB <b>[NEW]</b>	63-77 kW (86-105 PS)	FABIA TSI OCTAVIA TSI PRAKTIK TSI RAPID ROOMSTER TSI YETI TSI	09/09 →	<b>02-36650-01</b>  <b>08-40846-01</b> <sup>13</sup> <sup>35</sup>	<b>61-36650-00</b> 03F 103 383 E 72 Ø MLS 	<b>14-32323-01</b> WHT 004 790 (10x) 
1,2 CFWA <b>[NEW]</b>	55 kW (75 PS)	FABIA TDI PRAKTIK TDI ROOMSTER TDI	03/10 →	<b>02-40508-01</b> <sup>12</sup> <b>08-40849-01</b> <sup>14</sup>	<b>61-37820-00</b> 03P 103 383 C 82 Ø 1,55 mm 1 MLS <b>61-37820-10</b> 03P 103 383 D 82 Ø 1,63 mm 2 MLS <b>61-37820-20</b> 03P 103 383 E 82 Ø 1,71 mm 3 MLS 	<b>14-32299-02</b> WHT 002 131 (8x) 
1,3 135/8 136 L	43-45 kW (58-61 PS)	FAVORIT 136 RAPID 130	09/84-09/94	<b>01-27180-02</b> <sup>12</sup> <sup>13</sup> <b>02-27180-02</b> <sup>12</sup>	<b>61-27180-10</b> 114-092854 77 Ø 1,5 mm 	

<sup>12</sup> Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / junta para múltiple de admisión/de escape / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<b>70-31414-10</b> 	<b>12-31306-13</b> 036 109 675 (6x) <b>70-31306-00</b> 036 109 675 6x	<b>40-77570-00</b> 03D 129 717 B 3x 	<b>71-36101-00</b> 03D 253 039 B 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-34819-00 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM
<b>70-31414-10</b> 	<b>12-31306-08</b> 036 109 675 (12x) <b>70-31306-00</b> 036 109 675 12x	<b>40-77557-00</b> 03E 129 717 B 3x 	<b>71-36102-00</b> 03E 253 039 A 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-34819-00 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM
<b>70-31414-10</b> 	<b>12-31306-13</b> 036 109 675 (6x) <b>70-31306-00</b> 036 109 675 6x	<b>40-77570-00</b> 03D 129 717 B 3x 	<b>71-36101-00</b> 03D 253 039 B 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-34819-00 K</b> → 021 103 051 C 85x105x11 A SL LD PTFE ACM
<b>70-31414-10</b>  <b>71-40101-00</b> X 03F 103 483 A Metall 	<b>12-31306-07</b> 036 109 675 (8x) <b>70-31306-00</b> 036 109 675 8x	<b>71-40531-00</b> 03F 129 717 4x  <b>71-40534-00</b> 03F 129 717 A 1x 	<b>71-40498-00</b> 03F 253 041 P 	<b>70-31414-10</b> 	<b>81-34367-00 K</b> ← 038 103 085 A 32x47x10 A SL RD PTFE ACM <b>81-90059-00 K</b> → 036 103 171 B PTFE
<b>71-40508-00</b> 03P 103 483 	<b>12-31306-08</b> 036 109 675 (12x) <b>70-31306-00</b> 036 109 675 12x	<b>71-40479-00</b> 03P 129 717 	<b>71-40499-00</b> 03P 253 039 	<b>70-31414-10</b> 	<b>81-40538-00 N</b> 03L 103 085 32x47x10 A RD FPM
<b>71-36056-00</b> 047 103 483 	<b>12-22737-01</b> 113-028540 (8x) <b>70-22737-00</b> 113-028540 8x	<b>71-27203-10</b> <sup>7</sup> 114-095840 	<b>71-13061-00</b> 113-090920 	<b>81-26269-00 K</b> ← 42x58x11 A SL RD FPM <b>81-23708-40 K</b> → 068 103 051 P 85x105x11 A SL LD FPM	

<sup>14</sup> ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / sin retén cigüeñal / senza paraolio albero motore / без уплотнительного кольца коленчатого вала  
<sup>35</sup> enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene retén integrado / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



SKODA						
Ltr.						
1,4 AME AQW ATZ AZE AZF	08/99-05/03	FABIA 44-50 kW (60-68 PS)	02-36205-01 <sup>(12)</sup> 08-36087-01 <sup>(13)</sup>	61-36205-00 047 103 383 J 	14-32167-01 N 907 957 01 (5x) +N 907 958 01 (4x) +N 907 956 01 (1x) 	
1,4 AMF	04/03-03/08	FABIA TDI 55 kW (75 PS)	02-35128-01 <sup>(12)</sup>   08-36871-01 <sup>(13) (38)</sup>	61-31855-00 045 103 383 F 80,5 Ø 1,45 mm 1 MLS 61-31855-10 045 103 383 G 80,5 Ø 1,53 mm 2 MLS 61-31855-20 045 103 383 H 80,5 Ø 1,61 mm 3 MLS 	14-32121-02 038 103 384 (8x) 	
1,4 AUA AUB BBY BBZ BKY	10/99-03/08	FABIA 55-74 kW (75-100 PS)	02-34075-01 <sup>(12)</sup> 08-34320-01 <sup>(13) (38)</sup> 036 198 011	61-34075-00 036 103 383 AM 77,5 Ø MLS 	14-32120-01 036 103 384 B (10x) 	
1,4 AXP	08/00-12/10	OCTAVIA 55 kW (75 PS)	02-34075-01 <sup>(12)</sup> 08-34320-01 <sup>(13) (38)</sup> 036 198 011	61-34075-00 036 103 383 AM 77,5 Ø MLS 	14-32120-01 036 103 384 B (10x) 	
1,4 BCA	08/00-12/10	OCTAVIA 55 kW (75 PS)	02-34075-01 <sup>(12)</sup> 08-34320-01 <sup>(13) (38)</sup> 036 198 011	61-34075-00 036 103 383 AM 77,5 Ø MLS 	14-32120-01 036 103 384 B (10x) 	

<sup>(38)</sup> ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



71-36056-00 047 103 483 	12-26058-02 027 109 675 (8x) 70-26058-00 027 109 675 8x	71-36769-00 047 129 717 E 2x 	71-36086-00 047 253 050 71-36723-00 R 047 253 039 H 71-36724-00 L 047 253 039 J 	70-31414-10 	81-36787-00 K ← 047 103 085 42x58x8 A SL RD FPM 81-36788-00 K → 047 103 085 A 85x105x12 A SL LD FPM
71-37574-00 045 103 483 C 	12-26058-05 027 109 675 (6x) 70-26058-00 027 109 675 6x	71-34221-00 045 129 717 	71-34217-00 045 253 039 71-33199-00 1H0 253 115 A 	70-31414-10 	81-34366-00 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM 81-90010-00 K → 06A 103 171 A PTFE 81-34367-00 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
70-31414-10 	12-31306-12 036 109 675 (16x) 70-31306-00 036 109 675 16x	71-34204-00 036 129 717 E 4x 	71-34206-00 036 253 039 F 	70-31414-10 	81-34227-00 K ← 036 103 085 H 32x42x6 A SL RD FPM 81-34226-00 N 2x 036 103 085 A 27x42x8 A SL RD FPM
70-31414-10 	12-31306-12 036 109 675 (16x) 70-31306-00 036 109 675 16x	71-34204-00 036 129 717 E 4x 	71-34206-00 036 253 039 F 	70-31414-10 	81-34227-00 K ← 036 103 085 H 32x42x6 A SL RD FPM 81-90016-00 K → 030 103 171 K PTFE 01/02→ 81-34226-00 N 2x 036 103 085 A 27x42x8 A SL RD FPM
70-31414-10 	12-31306-12 036 109 675 (16x) 70-31306-00 036 109 675 16x	71-34204-00 036 129 717 E 4x 	71-34206-00 036 253 039 F 	70-31414-10 	81-34227-00 K ← 036 103 085 H 32x42x6 A SL RD FPM 81-90016-00 K → 030 103 171 K PTFE 81-34226-00 N 2x 036 103 085 A 27x42x8 A SL RD FPM



SKODA						
Ltr.						
1,4 BMS	59 kW (80 PS)	FABIA TDI ROOMSTER	09/06→	<b>02-37573-01</b> <sup>12</sup>  <b>08-36871-01</b> <sup>13 38</sup>	<b>61-31855-00</b> 045 103 383 F 80,5 Ø 1,45 mm 1 MLS <b>61-31855-10</b> 045 103 383 G 80,5 Ø 1,53 mm 2 MLS <b>61-31855-20</b> 045 103 383 H 80,5 Ø 1,61 mm 3 MLS 	<b>14-32121-02</b> 038 103 384 (8x) 
1,4 BNM BNV	51-59 kW (70-80 PS)	FABIA TDI ROOMSTER	10/05→	<b>02-37574-01</b> <sup>12</sup>  <b>08-36871-01</b> <sup>13 38</sup>	<b>61-31855-00</b> 045 103 383 F 80,5 Ø 1,45 mm 1 MLS <b>61-31855-10</b> 045 103 383 G 80,5 Ø 1,53 mm 2 MLS <b>61-31855-20</b> 045 103 383 H 80,5 Ø 1,61 mm 3 MLS 	<b>14-32121-02</b> 038 103 384 (8x) 
1,4 BUD BXW	59-63 kW (80-86 PS)	FABIA OCTAVIA ROOMSTER	06/04→	<b>02-34075-01</b> <sup>12</sup> <b>08-34320-01</b> <sup>13 38</sup> 036 198 011	<b>61-34075-00</b> 036 103 383 AM 77,5 Ø MLS 	<b>14-32120-01</b> 036 103 384 B (10x) 
1,4 CAVE CAXC CFB CTHE	92-132 kW (125-180 PS)	FABIA TSI SUPERB TSI	07/08→	<b>01-37045-01</b> <sup>12 13 38</sup>	<b>61-37045-00</b> 03C 103 383 R 77,5 Ø MLS 	<b>14-32277-01</b> WHT 000 912 (10x) 
1,4 CAXA	90 kW (122 PS)	OCTAVIA TSI RAPID YETI TSI	11/08→	<b>01-37045-01</b> <sup>12 13 38</sup>	<b>61-37045-00</b> 03C 103 383 R 77,5 Ø MLS 	<b>14-32277-01</b> WHT 000 912 (10x) 

<b>71-37573-00</b> 045 103 483 E 	<b>12-26058-05</b> 027 109 675 (6x) <b>70-26058-00</b> 027 109 675 6x	<b>71-34221-00</b> 045 129 717 	<b>71-37532-00</b> 045 253 039 B 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>71-37574-00</b> 045 103 483 C 	<b>12-26058-05</b> 027 109 675 (6x) <b>70-26058-00</b> 027 109 675 6x	<b>71-34221-00</b> 045 129 717 	<b>71-34217-00</b> 045 253 039  <b>71-33199-00</b> <sup>10</sup> 1H0 253 115 A 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90010-00 K</b> → 06A 103 171 A PTFE <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>70-31414-10</b> 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-34204-00</b> 4x 036 129 717 E 	<b>71-34206-00</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>81-34227-00 K</b> ← 038 103 085 H 32x42x6 A SL RD FPM <b>81-90021-00 K</b> → 030 103 171 S PTFE <b>81-34226-00 N</b> 2x 036 103 085 A 27x42x8 A SL RD FPM
<b>70-31414-10</b> 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-36116-00</b> 03C 129 717 C  <b>71-36068-00</b> <sup>10</sup> 4x 03C 129 717 A 	<b>71-36122-00</b> 03C 253 039 D 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90059-00 K</b> → 036 103 171 B PTFE
<b>70-31414-10</b> 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-36116-00</b> 03C 129 717 C  <b>71-36068-00</b> <sup>10</sup> 4x 03C 129 717 A 	<b>71-36122-00</b> 03C 253 039 D 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90059-00 K</b> → 036 103 171 B PTFE CAXA 010 452→

<sup>12</sup> Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / junta, carcasa de colector de admisión / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора

<sup>38</sup> ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
1,4 CGGA	59 kW (80 PS)	OCTAVIA	06/04→	<b>02-34075-01</b> <sup>12</sup> <b>08-34320-01</b> <sup>13 38</sup> 036 198 011	<b>61-34075-00</b> 036 103 383 AM 77,5 Ø MLS	<b>14-32120-01</b> 036 103 384 B (10x)
1,4 CHPA <b>[NEW]</b>	103 kW (140 PS)	OCTAVIA TSI	11/12→	<b>02-37800-01</b> <sup>12</sup> <b>08-42961-01</b> <sup>13 38</sup>	<b>61-37800-00</b> 04E 103 383 BJ 75 Ø MLS	<b>14-32385-01</b> WHT 004 926 (10x)
1,6 AEE	55 kW (75 PS)	FELICIA OCTAVIA	08/95-09/04	<b>02-31970-02</b> <sup>12</sup> 032 198 012 B <b>08-31414-02</b> <sup>13</sup> 030 198 011 A → AEE 562 757  <b>08-34325-01</b> <sup>13 35</sup> → AEE 562 758→	<b>61-31970-00</b> 030 103 383 AH 77,5 Ø 0,5 mm MLS	<b>14-32051-01</b> 032 103 384 (10x)
1,6 AEH AKL	74 kW (101 PS)	OCTAVIA	02/97-12/07	<b>02-31280-01</b> <sup>12</sup> 06A 198 012 <b>08-35053-01</b> <sup>13 38</sup> 06A 198 011	<b>61-31280-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS	<b>14-32126-01</b> 06A 103 384 C (10x)
1,6 AVU BFQ	75 kW (102 PS)	OCTAVIA	09/00-12/10	<b>02-31280-05</b> <sup>12</sup> <b>08-35053-02</b> <sup>13 35</sup>	<b>61-31280-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS	<b>14-32126-01</b> 06A 103 384 C (10x)

<sup>12</sup> enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene retén integrado / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала  
<sup>38</sup> ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



<b>70-31414-10</b> 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675	<b>71-34204-00</b> 036 129 717 E	4x	<b>71-34206-00</b> 036 253 039 F	<b>70-31414-10</b> 		
<b>81-34227-00 K</b> ← 036 103 085 H 32x42x6 A SL RD FPM <b>81-90059-00 K</b> → 036 103 171 B PTFE <b>81-34226-00 N</b> 2x 036 103 085 A 27x42x8 A SL RD FPM	<b>71-42813-00</b> 04E 103 483 H	<b>12-42741-01</b> 04E 109 675 (8x) +04E 109 675 A (8x) <b>70-42741-00</b> ES 8x 04E 109 675 <b>70-42742-00</b> AS 8x 04E 109 675 A	<b>71-34204-00</b> 036 129 717 E	4x	<b>71-42802-00</b> 04E 253 039 D	<b>70-31414-10</b> 	<b>81-42697-00 K</b> ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>81-42736-00 N</b> ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>81-42734-00 N</b> → 04E 103 085 24x39x8 A SL LD PTFE ACM
<b>15-31693-01</b> 030 103 483 K +030 103 533 F (3x)	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	<b>11-77542-01</b> 030 198 717	8x	<b>71-31046-00</b> 032 253 039 E	<b>70-31414-10</b> 	<b>81-19299-10 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM → AEE 562 757 <b>81-34227-00 K</b> ← 036 103 085 H 32x42x6 A SL RD FPM → AEE 562 758→ <b>81-23708-40 K</b> → 068 103 051 P 85x105x11 A SL LD FPM → AEE 562 757 <b>81-90000-00 K</b> → 028 103 171 B → AEE 562 758→ <b>81-19299-10 N</b> 068 103 085 E 32x47x10 A SL WD FPM	
<b>71-31691-00</b> 051 103 483 A	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	<b>71-34203-00</b> 06A 133 398 F	8x	<b>71-31957-00</b> 037 253 039 D	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90006-00 K</b> → 06B 103 171 B PTFE <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM	
<b>71-34096-00</b> 06B 103 483 L	<b>12-31306-07</b> 036 109 675 (8x) <b>70-31306-00</b> 036 109 675	<b>71-34203-00</b> 06A 133 398 F	8x	<b>71-34216-00</b> 06A 253 039 L <b>71-27331-30</b> 533 253 115 D	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90006-00 K</b> → 06B 103 171 B PTFE <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM	

AS Auslaßseite / exhaust side / côté échappement / lado de escape / lato scarico / сторона выпуска  
 ES Einlaßseite / intake side / côté admission / lado de admisión / lato aspirazione / сторона впуска



SKODA						
Ltr.						
1,6 BGU BSE BSF	75 kW (102 PS)	OCTAVIA	06/04→	<b>02-31280-05</b> ⑫ <b>08-35053-03</b> ⑬ ⑳	<b>61-31280-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS 	<b>14-32126-01</b> 06A 103 384 C (10x) 
1,6 BLF	85 kW (115 PS)	OCTAVIA FSI	02/04-10/08	<b>01-34280-01</b> ⑫ ⑬ ⑳ <b>02-34280-01</b> ⑫	<b>61-34280-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>14-32120-01</b> 036 103 384 B (10x) 
1,6 BTS	77 kW (105 PS)	FABIA ROOMSTER	09/06→	<b>01-34280-02</b> ⑫ ⑬ ⑳	<b>61-34280-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>14-32120-01</b> 036 103 384 B (10x) 
1,6 CAYA CAYB CAYC	55-77 kW (75-105 PS)	FABIA TDI RAPID ROOMSTER TDI SUPERB TDI YETI TDI	03/10→	<b>02-40983-01</b> ⑫   <b>08-40847-01</b> ⑬ ⑳	<b>61-36360-00</b> 03L 103 383 J 80,5 Ø 1,55 mm 1 □ MLS <b>61-36360-10</b> 03L 103 383 K 80,5 Ø 1,63 mm 2 □ MLS <b>61-36360-20</b> 03L 103 383 L 80,5 Ø 1,71 mm 3 □ MLS 	<b>14-32299-01</b> WHT 002 131 (10x) 

⑫ Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / junta, carcasa de colector de admisión / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора

⑳ enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene retén integrado / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>71-34096-00</b> 06B 103 483 L 	<b>12-31306-07</b> 036 109 675 (8x) <b>70-31306-00</b> 036 109 675 8x	<b>71-34203-00</b> 06A 133 398 F 4x  <b>71-36061-00</b> ⑩ 06A 133 227 B 4x 	<b>71-34216-00</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90006-10 K</b> → 06B 103 171 E <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>70-31414-10</b> 	<b>12-31306-01</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-36116-00</b> 03C 129 717 C  <b>71-36068-00</b> ⑩ 03C 129 717 A 4x 	<b>71-36122-00</b> 03C 253 039 D  <b>71-34148-00</b> 1J0 253 115 S	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90021-00 K</b> → 030 103 171 S PTFE
<b>70-31414-10</b> 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-34204-00</b> 036 129 717 E 4x 	<b>71-36122-00</b> 03C 253 039 D 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM
<b>15-40484-01</b> 03L 103 483 H +03L 103 070 A (4x)  <b>15-40486-01</b> 03L 103 483 C +03L 103 070 (4x)  <b>71-40484-00</b> 03L 103 483 H  <b>71-40486-00</b> 03L 103 483 C 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-40514-00</b> 03L 129 717 J 4x  <b>71-40524-00</b> 03L 129 717 H 4x 	<b>71-37422-00</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90052-00 K</b> → 03L 103 171 PTFE <b>81-40538-00 N</b> 03L 103 085 32x47x10 A RD FPM

⑳ ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
1,6 CAYC	77 kW (105 PS) OCTAVIA TDI	06/09→				
			02-40983-01 <sup>12</sup> 10/09→   08-40847-01 <sup>13 35</sup>	61-36360-00 03L 103 383 J 80,5 Ø 1,55 mm 1 MLS 61-36360-10 03L 103 383 K 80,5 Ø 1,63 mm 2 MLS 61-36360-20 03L 103 383 L 80,5 Ø 1,71 mm 3 MLS 	14-32299-01 WHT 002 131 (10x) 	
1,6 CCSA CHGA CMXA	75 kW (102 PS) OCTAVIA	06/04→	02-31280-05 <sup>12</sup> 08-35053-02 <sup>13 35</sup>	61-31280-00 06B 103 383 H 82,5 Ø 1,2 mm MLS 	14-32126-01 06A 103 384 C (10x) 	
1,6 CDE CDF	77 kW (105 PS)		01-37045-03 <sup>12 13 35</sup>	61-37045-00 03C 103 383 R 77,5 Ø MLS 	14-32330-01 WHT 000 675 (10x) 	
1,6 CFNA <b>[NEW]</b>	77 kW (105 PS) FABIA RAPID ROOMSTER	09/06→	01-34280-02 <sup>12 13 35</sup>	61-34280-00 03C 103 383 D 77,5 Ø MLS 	14-32120-01 036 103 384 B (10x) 	

<sup>35</sup> enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene retén integrado / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



15-40484-01 03L 103 483 H +03L 103 070 A (4x) 	12-31306-12 036 109 675 (16x) 70-31306-00 036 109 675 16x	71-40514-00 03L 129 717 J 4x  71-40524-00 03L 129 717 H 4x 	71-37422-00 03L 253 039 E 	70-31414-10 	81-34366-00 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM 81-90052-00 K → 03L 103 171 PTFE 81-34367-00 N 038 103 085 A 32x47x10 A SL RD PTFE ACM 10/09→ 81-40538-00 N 03L 103 085 32x47x10 A RD FPM 10/09→			
15-40486-01 03L 103 483 C +03L 103 070 (4x) 	71-40484-00 03L 103 483 H 	71-40486-00 03L 103 483 C 	71-34096-00 06B 103 483 L 	12-31306-07 036 109 675 (8x) 70-31306-00 036 109 675 8x	71-34203-00 06A 133 398 F 4x 	71-34216-00 06A 253 039 L 	70-31414-10 	81-34366-00 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM 81-90006-00 K → 06B 103 171 B PTFE 81-34367-00 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
70-31414-10 	12-31306-12 036 109 675 (16x) 70-31306-00 036 109 675 16x	71-40541-00 03C 253 039 E 	70-31414-10 	81-34366-00 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM				
70-31414-10 	12-31306-12 036 109 675 (16x) 70-31306-00 036 109 675 16x	71-34204-00 036 129 717 E 4x 	71-36122-00 03C 253 039 D 	70-31414-10 	81-34366-00 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM 81-90059-00 K → 036 103 171 B PTFE			

<sup>35</sup> ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач





SKODA						
Ltr.						
1,6 CLHA CLHB CRKB	66-81 kW (90-110 PS)	OCTAVIA TDI	11/12→	<b>02-10002-01</b> <sup>(12)</sup> 	<b>61-37840-00</b> 04L 103 383 C 80,5 Ø 1,55 mm MLS 1 <input type="checkbox"/> <b>61-37840-10</b> 04L 103 383 D 80,5 Ø 1,63 mm MLS 2 <input type="checkbox"/> <b>61-37840-20</b> 04L 103 383 E 80,5 Ø 1,71 mm MLS 3 <input type="checkbox"/> 	<b>14-32384-01</b> WHT 005 673 (10x) 
1,6 CLSA	77 kW (105 PS)			<b>01-37045-03</b> <sup>(12) (13) (38)</sup> 	<b>61-37045-00</b> 03C 103 383 R 77,5 Ø MLS 	<b>14-32330-01</b> WHT 000 675 (10x) 
1,8 ADR	92 kW (125 PS)			<b>02-31955-01</b> <sup>(12)</sup> <b>08-31956-01</b> <sup>(13)</sup> <b>08-31956-02</b> <sup>(13) (35)</sup> 	<b>61-31955-10</b> 058 103 383 Q 82,5 Ø MLS 	<b>14-32052-01</b> 058 103 385 A (10x) 
1,8 AGN	92 kW (125 PS)	OCTAVIA	→ 1U V 040 000 09/96-07/00	<b>02-31955-02</b> <sup>(12)</sup> 06A 198 012 A <b>08-35054-01</b> <sup>(13) (38)</sup> 06A 198 011 A <b>15-34364-01</b> <sup>(8)</sup> 058 198 217	<b>61-31955-10</b> 058 103 383 Q 82,5 Ø MLS 	<b>14-32131-01</b> 06A 103 385 C (10x) → AGN 107 000 <b>14-32124-01</b> 06A 103 385 A (10x) → AGN 107 001 →
1,8 AGN	92 kW (125 PS)	OCTAVIA	1U W 000 001 → 09/96-07/00	<b>02-31955-03</b> <sup>(12)</sup> <b>08-35054-01</b> <sup>(13) (38)</sup> 06A 198 011 A <b>15-34364-01</b> <sup>(8)</sup> 058 198 217	<b>61-31955-10</b> 058 103 383 Q 82,5 Ø MLS 	<b>14-32131-01</b> 06A 103 385 C (10x) → AGN 107 000 <b>14-32124-01</b> 06A 103 385 A (10x) → AGN 107 001 →

<sup>(12)</sup> Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / junta para tensor cadena de distribución / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала  
<sup>(13)</sup> enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene retén integrado / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>15-42759-01</b> 03L 103 483 S +04L 103 070 (4x) 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-42811-00</b> 04L 129 717 B 	<b>71-42816-00</b> 04L 253 039 B 	<b>70-31414-10</b> 	<b>81-42306-00 K</b> → 04L 103 171 PTFE <b>81-40538-00 N</b> 03L 103 085 32x47x10 A RD FPM
<b>70-31414-10</b> 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-34204-00</b> 036 129 717 E 4x 	<b>71-40541-00</b> 03C 253 039 E 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90059-00 K</b> → 036 103 171 B PTFE
<b>15-31946-01</b> 058 198 025 A 	<b>12-31306-03</b> 036 109 675 (20x) <b>70-31306-00</b> 036 109 675 20x	<b>71-31986-00</b> 058 129 717 B 	<b>71-31958-00</b> 058 253 039 L 	<b>70-31414-10</b> 	<b>81-19299-10 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>81-23708-40 K</b> → 068 103 051 P 85x105x11 A SL LD FPM <b>81-90000-00 K</b> → 028 103 171 B <b>81-19299-10 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>15-31946-01</b> 058 198 025 A 	<b>12-31306-03</b> 036 109 675 (20x) <b>70-31306-00</b> 036 109 675 20x	<b>71-31986-00</b> 058 129 717 B 	<b>71-31958-00</b> 058 253 039 L 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90010-00 K</b> → 06A 103 171 A PTFE <b>81-34367-00 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>15-31946-01</b> 058 198 025 A 	<b>12-31306-03</b> 036 109 675 (20x) <b>70-31306-00</b> 036 109 675 20x	<b>71-34097-00</b> 06A 133 398 D 4x 	<b>71-31958-00</b> 058 253 039 L 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90010-00 K</b> → 06A 103 171 A PTFE <b>81-34367-00 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM

<sup>(38)</sup> ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
1,8 AGU ARX ARZ AUM AUQ AWT	110-132 kW (150-180 PS)	OCTAVIA T SUPERB T	08/97-12/10	<b>02-31955-02</b> ⑫ 06A 198 012 A <b>08-35054-01</b> ⑬ ⑳ 06A 198 011 A <b>15-34364-01</b> ⑧ 058 198 217	<b>61-31955-10</b> 058 103 383 Q 82,5 Ø MLS 	<b>14-32124-01</b> 06A 103 385 A (10x) 
1,8 BZB	118 kW (160 PS)	OCTAVIA TSI SUPERB TSI	06/07→	<b>02-37475-01</b> ⑫ <b>08-39129-01</b> ⑬ ⑳	<b>61-37475-00</b> 06H 103 383 AD 83 Ø MLS 	<b>14-32276-01</b> 06D 103 385 D (10x) 
1,8 CDA CDAB	112-118 kW (152-160 PS)	OCTAVIA TSI SUPERB TSI YETI TSI	06/07→	<b>02-37475-01</b> ⑫ <b>08-39129-01</b> ⑬ ⑳	<b>61-37475-00</b> 06H 103 383 AD 83 Ø MLS 	<b>14-32276-01</b> 06D 103 385 D (10x)  <b>14-32383-01</b> WHT 005 305 (10x) 
1,9 AEF	47 kW (64 PS)	FELICIA D	10/95-04/02	<b>02-28777-03</b> ⑫ 028 198 012 E  <b>08-23134-03</b> ⑬ 028 198 011 D → AEF 265 000  <b>08-23134-04</b> ⑬ ⑳ → AEF 265 001→ 	<b>61-31225-30</b> 028 103 383 BH 81 Ø 1,53 mm 1 □ MLS <b>61-31225-40</b> 028 103 383 BJ 81 Ø 1,57 mm 2 □ MLS <b>61-31225-50</b> 028 103 383 BK 81 Ø 1,61 mm 3 □ MLS 	<b>14-32047-01</b> 068 103 384 A (10x) 
1,9 AEY	47 kW (64 PS)			<b>02-31257-02</b> ⑫ 028 198 012 F  <b>08-23134-03</b> ⑬ 028 198 011 D → AEY 050 000  <b>08-23134-04</b> ⑬ ⑳ → AEY 050 001→ 	<b>61-33120-30</b> 028 103 383 BL 81 Ø 1,45 mm 1 □ MLS <b>61-33120-40</b> 028 103 383 BM 81 Ø 1,53 mm 2 □ MLS <b>61-33120-50</b> 028 103 383 BN 81 Ø 1,61 mm 3 □ MLS 	<b>14-32047-01</b> 068 103 384 A (10x) 

⑫ Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / junta para tensor cadena de distribución / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала  
 ⑬ enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene retén integrado / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>15-31946-01</b> 058 198 025 A 	<b>12-31306-03</b> 036 109 675 (20x) <b>70-31306-00</b> 036 109 675 20x	<b>71-31986-00</b> 058 129 717 B 	<b>71-31958-00</b> 058 253 039 L 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90010-00 K</b> → 06A 103 171 A PTFE <b>81-34367-00 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>70-31414-10</b> 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-37583-00</b> 06J 129 717 	<b>71-37511-00</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>81-37608-00 K</b> ← 06H 103 085 G 45x60x8 AB SL RD FPM <b>81-90037-00 K</b> → 06H 103 171 F PTFE
<b>70-31414-10</b> 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-36072-00</b> 06F 129 717 D  <b>71-37583-00</b> 06J 129 717 	<b>71-37511-00</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>81-37608-00 K</b> ← 06H 103 085 G 45x60x8 AB SL RD FPM <b>81-90037-00 K</b> → 06H 103 171 F PTFE
<b>15-28777-01</b> 028 198 025 	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675 8x	<b>71-28781-10</b> 028 129 717 D 	<b>71-28451-00</b> 037 253 039 	<b>71-31943-00</b> 037 115 220 B 	<b>81-19299-10 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>81-23708-40 K</b> → 068 103 051 P 85x105x11 A SL LD FPM → AEF 265 000 <b>81-90000-00 K</b> → 028 103 171 B → AEF 265 001→ <b>81-19299-10 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>15-31257-01</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x) 	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675 8x	<b>71-28781-10</b> 028 129 717 D 	<b>71-27898-20</b> 026 129 589 A 4x 	<b>71-33138-00</b> 044 103 609 D Gummi 	<b>81-19299-10 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>81-23708-40 K</b> → 068 103 051 P 85x105x11 A SL LD FPM → AEY 050 000 <b>81-90000-00 K</b> → 028 103 171 B → AEY 050 001→ <b>81-19299-10 N</b> 068 103 085 E 32x47x10 A SL WD FPM

⑳ ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA										
Ltr.										
1,9 AGP	50 kW (68 PS) OCTAVIA SDI	06/97-12/03	<b>02-33838-01</b> <sup>12</sup> 038 198 012   <b>08-31414-03</b> <sup>13 38</sup> 038 198 011 	<b>61-31325-00</b> 038 103 383 G 80,5 Ø 1,45 mm 1 MLS →AGP 028 000 <b>61-31325-10</b> 038 103 383 F 80,5 Ø 1,53 mm 2 MLS →AGP 028 000 <b>61-31325-20</b> 038 103 383 E 80,5 Ø 1,61 mm 3 MLS →AGP 028 000  <b>61-31980-00</b> 038 103 383 AL 80,5 Ø 1,47 mm 1 MLS →AGP 028 001→ <b>61-31980-10</b> 038 103 383 AM 80,5 Ø 1,57 mm 2 MLS →AGP 028 001→ <b>61-31980-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS →AGP 028 001→ 	<b>14-32047-01</b> 068 103 384 A (10x) 	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	<b>71-28781-10</b> 028 129 717 D 	<b>71-27898-20</b> R 2x 026 129 589 A  <b>71-28186-20</b> L 2x 034 129 589 B 	<b>70-31414-10</b> 	<b>81-24292-10</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>81-90010-00</b> K → 06A 103 171 A PTFE <b>81-19299-10</b> N 068 103 085 E 32x47x10 A SL WD FPM

<sup>38</sup> ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA													
Ltr.													
1,9 AGR	66 kW (90 PS) OCTAVIA TDI	09/96-03/10	<b>02-33838-01</b> <sup>12</sup> 038 198 012   <b>08-31414-03</b> <sup>13 38</sup> 038 198 011 	<b>61-31325-00</b> 038 103 383 G 80,5 Ø 1,45 mm 1 MLS → AGR 151 000 <b>61-31325-10</b> 038 103 383 F 80,5 Ø 1,53 mm 2 MLS → AGR 151 000 <b>61-31325-20</b> 038 103 383 E 80,5 Ø 1,61 mm 3 MLS → AGR 151 000  <b>61-31980-00</b> 038 103 383 AL 80,5 Ø 1,47 mm 1 MLS → AGR 151 001→ <b>61-31980-10</b> 038 103 383 AM 80,5 Ø 1,57 mm 2 MLS → AGR 151 001→ <b>61-31980-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS → AGR 151 001→ 	<b>14-32047-01</b> 068 103 384 A (10x) 			<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	8x	<b>71-28781-10</b> 028 129 717 D 	<b>71-27898-20</b> R 2x 026 129 589 A  <b>71-28186-20</b> L 2x 034 129 589 B 	<b>70-31414-10</b> 	<b>81-24292-10</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>81-90010-00</b> K → 06A 103 171 A PTFE <b>81-19299-10</b> N 068 103 085 E 32x47x10 A SL WD FPM

<sup>38</sup> ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
1,9 AHF	81 kW (110 PS) OCTAVIA TDI	08/97-01/06				
			<b>02-33838-01</b> <sup>12</sup> 038 198 012   <b>08-31414-03</b> <sup>13 38</sup> 038 198 011 	<b>61-31325-00</b> 038 103 383 G 80,5 Ø 1,45 mm 1 MLS → AHF 140 000 <b>61-31325-10</b> 038 103 383 F 80,5 Ø 1,53 mm 2 MLS → AHF 140 000 <b>61-31325-20</b> 038 103 383 E 80,5 Ø 1,61 mm 3 MLS → AHF 140 000  <b>61-31980-00</b> 038 103 383 AL 80,5 Ø 1,47 mm 1 MLS → AHF 140 001→ <b>61-31980-10</b> 038 103 383 AM 80,5 Ø 1,57 mm 2 MLS → AHF 140 001→ <b>61-31980-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS → AHF 140 001→ 	<b>14-32047-01</b> 068 103 384 A (10x) 	
1,9 ALH	66 kW (90 PS) OCTAVIA TDI	09/96-03/10	<b>02-33838-01</b> <sup>12</sup> 038 198 012   <b>08-31414-03</b> <sup>13 38</sup> 038 198 011 	<b>61-31980-00</b> 038 103 383 AL 80,5 Ø 1,47 mm 1 MLS <b>61-31980-10</b> 038 103 383 AM 80,5 Ø 1,57 mm 2 MLS <b>61-31980-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS 	<b>14-32047-01</b> 068 103 384 A (10x) 	

	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	<b>71-28781-10</b> 028 129 717 D 	<b>71-27898-20</b> R 2x 026 129 589 A  <b>71-28186-20</b> L 2x 034 129 589 B 	<b>70-31414-10</b> 	<b>81-24292-10</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>81-90010-00</b> K → 06A 103 171 A PTFE <b>81-19299-10</b> N 068 103 085 E 32x47x10 A SL WD FPM
	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	<b>71-28781-10</b> 028 129 717 D 	<b>71-27898-20</b> R 2x 026 129 589 A  <b>71-28186-20</b> L 2x 034 129 589 B 	<b>70-31414-10</b> 	<b>81-24292-10</b> K ← 054 115 147 B 35x48x10 A SL RD FPM <b>81-90010-00</b> K → 06A 103 171 A PTFE <b>81-19299-10</b> N 068 103 085 E 32x47x10 A SL WD FPM

<sup>38</sup> ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
1,9 AQM	50 kW (68 PS)	OCTAVIA SDI	06/97-12/03	<b>02-33838-02</b> <sup>12</sup>   <b>08-31414-03</b> <sup>13 38</sup>  	<b>61-31980-00</b> 038 103 383 AL 80,5 Ø 1,47 mm 1 MLS <b>61-31980-10</b> 038 103 383 AM 80,5 Ø 1,57 mm 2 MLS <b>61-31980-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS 	<b>14-32047-01</b> 068 103 384 A (10x) 
1,9 ASV	81 kW (110 PS)	OCTAVIA TDI	08/97-01/06	<b>02-33838-01</b> <sup>12</sup>   <b>08-31414-03</b> <sup>13 38</sup>  	<b>61-31980-00</b> 038 103 383 AL 80,5 Ø 1,47 mm 1 MLS <b>61-31980-10</b> 038 103 383 AM 80,5 Ø 1,57 mm 2 MLS <b>61-31980-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS 	<b>14-32047-01</b> 068 103 384 A (10x) 
1,9 ASY	47 kW (64 PS)	FABIA SDI	11/99-03/08	<b>02-34302-02</b> <sup>12</sup>   <b>08-35038-01</b> <sup>13 35</sup> 	<b>61-31980-00</b> 038 103 383 AL 80,5 Ø 1,47 mm 1 MLS <b>61-31980-10</b> 038 103 383 AM 80,5 Ø 1,57 mm 2 MLS <b>61-31980-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS 	<b>14-32047-01</b> 068 103 384 A (10x) 

<sup>35</sup> enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene retén integrado / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	8x <b>71-28781-10</b> 028 129 717 D 	<b>71-31957-00</b> 037 253 039 D  <b>71-27909-10</b> 155 253 115 	<b>70-31414-10</b> 	<b>81-24292-10 K ←</b> 054 115 147 B 35x48x10 A SL RD FPM <b>81-90010-00 K →</b> 06A 103 171 A PTFE <b>81-19299-10 N</b> 068 103 085 E 32x47x10 A SL WD FPM
	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	8x <b>71-28781-10</b> 028 129 717 D 	<b>71-27898-20 R</b> 2x 026 129 589 A  <b>71-28186-20 L</b> 2x 034 129 589 B  <b>71-31957-00</b> 037 253 039 D  <b>71-33841-00</b> 3A0 253 115 	<b>70-31414-10</b> 	<b>81-24292-10 K ←</b> 054 115 147 B 35x48x10 A SL RD FPM <b>81-90010-00 K →</b> 06A 103 171 A PTFE <b>81-19299-10 N</b> 068 103 085 E 32x47x10 A SL WD FPM
	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	8x <b>71-28781-10</b> 028 129 717 D 	<b>71-27898-20 L</b> 2x 026 129 589 A  <b>71-28186-20 R</b> 2x 034 129 589 B  <b>71-27909-10</b> 155 253 115 	<b>70-31414-10</b> 	<b>81-34366-00 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90010-00 K →</b> 06A 103 171 A PTFE <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM

<sup>38</sup> ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
1,9 ASZ ATD AXR	74-96 kW (100-130 PS) FABIA TDI OCTAVIA TDI ROOMSTER TDI	01/00-12/10		<b>02-34302-01</b> <sup>12</sup>  <b>08-35038-01</b> <sup>13 35</sup>	<b>61-34250-00</b> 038 103 383 DE 81 Ø 1,45 mm 1 MLS <b>61-34250-10</b> 038 103 383 DF 81 Ø 1,53 mm 2 MLS <b>61-34250-20</b> 038 103 383 DG 81 Ø 1,61 mm 3 MLS 	<b>14-32121-01</b> 038 103 384 (10x) 
1,9 AVB AVF AWX BLT BPZ BSV BSW	74-96 kW (101-130 PS) FABIA TDI ROOMSTER SUPERB TDI	12/01→		<b>02-34302-01</b> <sup>12</sup>  <b>08-35038-01</b> <sup>13 35</sup>	<b>61-34250-00</b> 038 103 383 DE 81 Ø 1,45 mm 1 MLS <b>61-34250-10</b> 038 103 383 DF 81 Ø 1,53 mm 2 MLS <b>61-34250-20</b> 038 103 383 DG 81 Ø 1,61 mm 3 MLS 	<b>14-32121-01</b> 038 103 384 (10x) 
1,9 BJB BKC BXE	77 kW (105 PS) OCTAVIA TDI SUPERB TDI	06/04-12/10		<b>02-34302-01</b> <sup>12</sup>  <b>08-35038-02</b> <sup>13 35</sup>	<b>61-34250-00</b> 038 103 383 DE 81 Ø 1,45 mm 1 MLS <b>61-34250-10</b> 038 103 383 DF 81 Ø 1,53 mm 2 MLS <b>61-34250-20</b> 038 103 383 DG 81 Ø 1,61 mm 3 MLS 	<b>14-32121-01</b> 038 103 384 (10x) 

<b>71-35884-00</b> 038 103 483 D 	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675 8x	<b>71-28781-10</b> 028 129 717 D 	<b>71-27898-20</b> R 2x 026 129 589 A  <b>71-28186-20</b> L 2x 034 129 589 B  <b>71-33841-00</b> 3A0 253 115 	<b>70-31414-10</b> 	<b>81-34366-00</b> K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90010-00</b> K → 06A 103 171 A PTFE <b>81-34367-00</b> N 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>71-35884-00</b> 038 103 483 D 	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675 8x	<b>71-28781-10</b> 028 129 717 D 	<b>71-31957-00</b> 037 253 039 D  <b>71-33841-00</b> 3A0 253 115 	<b>70-31414-10</b> 	<b>81-34366-00</b> K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90010-00</b> K → 06A 103 171 A PTFE <b>81-34367-00</b> N 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>71-35884-00</b> 038 103 483 D 	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675 8x	<b>71-28781-10</b> 028 129 717 D 	<b>71-31957-00</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>81-34366-00</b> K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90018-00</b> K → 038 103 171 S PTFE <b>81-34367-00</b> N 038 103 085 A 32x47x10 A SL RD PTFE ACM

<sup>12</sup> enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene retén integrado / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



SKODA						
Ltr.						
1,9 BLS	77 kW (105 PS)	FABIA TDI OCTAVIA TDI ROOMSTER SUPERB TDI	06/04→	<b>02-37594-01</b> <sup>12</sup>  <b>08-35038-02</b> <sup>13 35</sup>	<b>61-34250-00</b> 038 103 383 DE 81 Ø 1,45 mm 1 MLS <b>61-34250-10</b> 038 103 383 DF 81 Ø 1,53 mm 2 MLS <b>61-34250-20</b> 038 103 383 DG 81 Ø 1,61 mm 3 MLS 	<b>14-32121-01</b> 038 103 384 (10x) 
2,0 AEG	85 kW (116 PS)	OCTAVIA	04/99-05/07	<b>08-35038-01</b> <sup>13 35</sup>	<b>61-34140-10</b> 06A 103 383 AN MLS 	<b>14-32126-01</b> 06A 103 384 C (10x) 
2,0 APK AQY AZH	85 kW (116 PS)	FABIA OCTAVIA	04/99-03/08	<b>02-34140-02</b> <sup>12</sup> <b>08-35038-01</b> <sup>13 35</sup>	<b>61-34140-10</b> 06A 103 383 AN MLS 	<b>14-32126-01</b> 06A 103 384 C (10x) 
2,0 AZJ	85 kW (116 PS)	OCTAVIA	04/99-05/07	<b>08-35038-01</b> <sup>13 35</sup>	<b>61-34140-10</b> 06A 103 383 AN MLS 	<b>14-32126-01</b> 06A 103 384 C (10x) 
2,0 AZL	85 kW (116 PS)	FABIA	12/99-03/08	<b>02-34140-03</b> <sup>12</sup> <b>08-35038-01</b> <sup>13 35</sup>	<b>61-34140-10</b> 06A 103 383 AN MLS 	<b>14-32126-01</b> 06A 103 384 C (10x) 

<sup>12</sup> Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / junta, carcasa de colector de admisión / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>71-37594-00</b> 03G 103 483 D 	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	<b>71-28781-10</b> 028 129 717 D 8x 	<b>71-37533-00</b> 03G 253 039 A 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90018-00 K</b> → 038 103 171 S PTFE <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>71-34212-00</b> 06A 103 483 C 	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	<b>40-76854-00</b> 4x 06A 129 717 D 	<b>71-34216-00</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90010-00 K</b> → 06A 103 171 A PTFE <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>71-31691-00</b> 051 103 483 A  2 Dichtlippen	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	<b>71-31983-00</b> 037 129 717 C  <b>71-34222-00</b> <sup>10</sup> 06A 129 717 	<b>71-34216-00</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90010-00 K</b> → 06A 103 171 A PTFE <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>71-34212-00</b> 06A 103 483 C 	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	<b>71-34203-00</b> 4x 06A 133 398 F  <b>71-36061-00</b> <sup>10</sup> 4x 06A 133 227 B 	<b>71-34216-00</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90010-00 K</b> → 06A 103 171 A PTFE <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>71-34212-00</b> 06A 103 483 C 	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	<b>71-31983-00</b> 037 129 717 C  <b>71-34222-00</b> <sup>10</sup> 06A 129 717 	<b>71-34216-00</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90010-00 K</b> → 06A 103 171 A PTFE <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM

<sup>35</sup> enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene retén integrado / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала





SKODA						
Ltr.						
2,0 AZM	85 kW (115 PS)	SUPERB	12/01-03/08	<b>02-34140-01</b> <sup>12</sup> <b>08-35038-01</b> <sup>13 35</sup>	<b>61-34140-10</b> 06A 103 383 AN MLS 	<b>14-32126-01</b> 06A 103 384 C (10x) 
2,0 AZV BKD	100-103 kW (136-140 PS)	OCTAVIA TDI SUPERB TDI	02/04→	<b>02-36041-01</b> <sup>12</sup>  <b>08-35038-02</b> <sup>13 35</sup>	<b>61-33770-00</b> 03G 103 383 82 Ø 1,55 mm 1 MLS <b>61-33770-10</b> 03G 103 383 A 82 Ø 1,63 mm 2 MLS <b>61-33770-20</b> 03G 103 383 B 82 Ø 1,71 mm 3 MLS 	<b>14-32195-01</b> 03G 103 384 (10x) 
2,0 BLR BLX BLY BVX BVY BVZ	110 kW (150 PS)	OCTAVIA FSI	11/04→	<b>02-36030-02</b> <sup>12</sup> <b>08-35053-04</b> <sup>13 38</sup>	<b>61-36030-00</b> 06D 103 383 L MLS 	<b>14-32197-01</b> 06D 103 385 (10x) 
2,0 BMM BMP	103 kW (140 PS)	OCTAVIA TDI SUPERB TDI	11/05→	<b>02-37594-01</b> <sup>12</sup>  <b>08-35038-02</b> <sup>13 35</sup>	<b>61-34810-00</b> 038 103 383 CP 82 Ø 1,45 mm 1 MLS <b>61-34810-10</b> 038 103 383 CQ 82 Ø 1,53 mm 2 MLS <b>61-34810-20</b> 038 103 383 CR 82 Ø 1,61 mm 3 MLS 	<b>14-32121-01</b> 038 103 384 (10x) 

<sup>35</sup> enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene retén integrado / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>71-31691-00</b> 051 103 483 A 	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	<b>71-34208-00</b> 06B 129 717 A 4x 	<b>71-31957-00</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90010-00 K</b> → 06A 103 171 A PTFE <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>71-36041-00</b> 03G 103 483 	<b>12-31306-01</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675	<b>71-36121-00</b> 03G 129 717 B  <b>71-37563-00</b> 03G 129 717 C 	<b>71-38428-00</b> 03L 253 039 B 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90018-00 K</b> → 038 103 171 S PTFE <b>81-34367-00 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>71-36047-00</b> 06D 103 483 E 	<b>12-31306-01</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675	<b>71-36071-00</b> 06D 129 717 D 	<b>71-34214-00</b> 06B 253 039 E 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90006-00 K</b> → 06B 103 171 B PTFE <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>71-37594-00</b> 03G 103 483 D 	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675	<b>71-28781-10</b> 028 129 717 D 	<b>71-37533-00</b> 03G 253 039 A 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90018-00 K</b> → 038 103 171 S PTFE <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM

<sup>38</sup> ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
2,0 BMN	125 kW (170 PS) OCTAVIA TDI	04/06→				
			02-36972-01 <sup>(12)</sup>  08-35038-02 <sup>(13) (35)</sup>	61-33770-00 03G 103 383 82 Ø 1,55 mm 1 MLS 61-33770-10 03G 103 383 A 82 Ø 1,63 mm 2 MLS 61-33770-20 03G 103 383 B 82 Ø 1,71 mm 3 MLS 	14-32195-01 03G 103 384 (10x) 	
2,0 BSS BWW	91-103 kW (124-140 PS) SUPERB TDI	10/05→				
			02-34302-01 <sup>(12)</sup>  08-35038-01 <sup>(13) (35)</sup>	61-34810-00 038 103 383 CP 82 Ø 1,45 mm 1 MLS 61-34810-10 038 103 383 CQ 82 Ø 1,53 mm 2 MLS 61-34810-20 038 103 383 CR 82 Ø 1,61 mm 3 MLS 	14-32121-01 038 103 384 (10x) 	
2,0 BWA	147 kW (200 PS) OCTAVIA RS	10/05→				
			02-36005-01 <sup>(12)</sup> 08-35054-02 <sup>(13) (35)</sup>	61-36005-00 06F 103 383 G MLS 	14-32276-01 06D 103 385 D (10x) 	
2,0 CBBB CBDB CEGA	103-125 kW (140-170 PS) OCTAVIA TDI SUPERB TDI YETI TDI	04/06→				
			02-38931-01 <sup>(12)</sup>  08-39084-01 <sup>(13) (35)</sup>	61-38190-00 03L 103 383 82 Ø 1,55 mm 1 MLS 61-38190-10 03L 103 383 A 82 Ø 1,63 mm 2 MLS 61-38190-20 03L 103 383 B 82 Ø 1,71 mm 3 MLS 	14-32299-01 WHT 002 131 (10x) 	

<sup>(35)</sup> enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene retén integrado / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



71-36972-00 03G 103 483 C 	12-31306-01 036 109 675 (16x) 70-31306-00 036 109 675 16x	71-36121-00 03G 129 717 B  71-37563-00 03G 129 717 C 	71-38429-00 03G 253 039 E 	70-31414-10 	81-34366-00 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM 81-90018-00 K → 038 103 171 S PTFE 81-34367-00 N 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
71-35884-00 038 103 483 D 	12-26058-02 027 109 675 (8x) 70-26058-00 027 109 675 8x	71-28781-10 028 129 717 D 	71-31957-00 037 253 039 D 	70-31414-10 	81-34366-00 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM 81-90010-00 K → 06A 103 171 A PTFE 81-34367-00 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
71-36774-00 06F 103 483 D 	12-31306-12 036 109 675 (16x) 70-31306-00 036 109 675 16x	71-36072-00 06F 129 717 D 	71-37511-00 06F 253 039 F 	70-31414-10 	81-34366-00 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM 81-90010-00 K → 06A 103 171 A PTFE 81-34367-00 N 038 103 085 A 32x47x10 A SL RD PTFE ACM
71-38931-00 03L 103 483 	12-31306-12 036 109 675 (16x) 70-31306-00 036 109 675 16x	71-38929-00 03L 129 717 	71-38428-00 03L 253 039 B 	70-31414-10 	81-34366-00 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM 81-90052-00 K → 03L 103 171 PTFE 81-34367-00 N 038 103 085 A 32x47x10 A SL RD PTFE ACM



SKODA						
Ltr.						
2,0 CCZA	10/05→	147 kW (200 PS)	OCTAVIA RS SUPERB TSI	<b>02-37475-01</b> <sup>12</sup> <b>08-39129-01</b> <sup>13 35</sup>	<b>61-37475-00</b> 06H 103 383 AD 83 Ø MLS 	<b>14-32276-01</b> 06D 103 385 D (10x)  <b>14-32383-01</b> WHT 005 305 (10x) 
2,0 CFFB CFHA CFHC CFHF CFJA CLCA CLCB CLJA	02/04→	81-125 kW (110-170 PS)	OCTAVIA TDI SUPERB TDI YETI TDI	<b>02-40486-01</b> <sup>12</sup>  <b>08-40848-01</b> <sup>13 35</sup>	<b>61-37600-00</b> 03L 103 383 BM 82 Ø 1,55 mm 1 MLS <b>61-37600-10</b> 03L 103 383 BN 82 Ø 1,63 mm 2 MLS <b>61-37600-20</b> 03L 103 383 BP 82 Ø 1,71 mm 3 MLS 	<b>14-32299-01</b> WHT 002 131 (10x) 
2,0 CFGB <b>[NEW]</b>	07/08→	125 kW (170 PS)	SUPERB TDI	<b>02-40486-04</b> <sup>12</sup>  <b>08-40848-02</b> <sup>13 38</sup>	<b>61-37600-00</b> 03L 103 383 BM 82 Ø 1,55 mm 1 MLS <b>61-37600-10</b> 03L 103 383 BN 82 Ø 1,63 mm 2 MLS <b>61-37600-20</b> 03L 103 383 BP 82 Ø 1,71 mm 3 MLS 	<b>14-32299-01</b> WHT 002 131 (10x) 
2,0 CGM		147 kW (200 PS)		<b>02-37475-01</b> <sup>12</sup>	<b>61-37475-00</b> 06H 103 383 AD 83 Ø MLS 	<b>14-32276-01</b> 06D 103 385 D (10x) 
2,0 CGZ		88 kW (120 PS)			<b>61-34140-10</b> 06A 103 383 AN MLS 	<b>14-32126-01</b> 06A 103 384 C (10x) 

<sup>35</sup> enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene retén integrado / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>70-31414-10</b> 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-36072-00</b> 06F 129 717 D 	<b>71-37511-00</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>81-37608-00 K</b> ← 06H 103 085 G 45x60x8 AB SL RD FPM <b>81-90037-00 K</b> → 06H 103 171 F PTFE
<b>15-40486-01</b> 03L 103 483 C +03L 103 070 (4x) 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-40507-00</b> 03L 129 717 E 	<b>71-37422-00</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90052-00 K</b> → 03L 103 171 PTFE <b>81-40538-00 N</b> 03L 103 085 32x47x10 A RD FPM
<b>15-40486-01</b> 03L 103 483 C +03L 103 070 (4x) 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-40507-00</b> 03L 129 717 E 	<b>71-42823-00</b> 04L 253 039 D 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90052-00 K</b> → 03L 103 171 PTFE <b>81-40538-00 N</b> 03L 103 085 32x47x10 A RD FPM
<b>70-31414-10</b> 	<b>12-31306-12</b> 036 109 675 (16x) <b>70-31306-00</b> 036 109 675 16x	<b>71-36072-00</b> 06F 129 717 D 	<b>71-37511-00</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>81-37608-00 K</b> ← 06H 103 085 G 45x60x8 AB SL RD FPM
<b>71-34212-00</b> 06A 103 483 C 	<b>12-26058-02</b> 027 109 675 (8x) <b>70-26058-00</b> 027 109 675 8x	<b>40-76854-00</b> 4x 06A 129 717 D 	<b>71-34216-00</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>81-34366-00 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>81-90010-00 K</b> → 06A 103 171 A PTFE <b>81-34367-00 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM

<sup>38</sup> ohne Wedi Getriebes / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / sin retén en el lado de la transmisión / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
2,5 AYM	114 kW (155 PS) SUPERB TDI	12/01-08/03				
			02-34088-01 <sup>(12)</sup> 2x 	61-34145-00 2x 059 103 383 BQ 79 Ø 1,1 mm 1 MLS 61-34145-10 2x 059 103 383 BR 79 Ø 1,15 mm 2 MLS 61-34145-20 2x 059 103 383 BS 79 Ø 1,2 mm 3 	14-32059-02 2x 059 103 384 (8x) 	
			08-31717-01 <sup>(13)</sup> 			
2,5 BDG	120 kW (163 PS) SUPERB TDI	06/03-03/08				
			02-34088-01 <sup>(12)</sup> 2x 	61-34145-00 2x 059 103 383 BQ 79 Ø 1,1 mm 1 MLS 61-34145-10 2x 059 103 383 BR 79 Ø 1,15 mm 2 MLS 61-34145-20 2x 059 103 383 BS 79 Ø 1,2 mm 3 	14-32196-01 2x 057 103 384 A (8x) 	
			08-31717-01 <sup>(13)</sup> 			
2,8 AMX BBG	140-142 kW (190-193 PS) SUPERB SUPERB V6	12/01-03/08				
			02-31875-02 2x 078 198 012 F +068 103 085 E (2x) 15-34364-01 <sup>(8)</sup> 2x 058 198 217	61-31875-00 2x 078 103 383 L 83,5 Ø MLS 	14-32125-02 2x 078 103 385 K (8x) 	
3,6 CDVA	191 kW (260 PS) SUPERB	11/08→				
			02-36430-02 <sup>(12)</sup>	61-36430-00 03H 103 383 H 85 Ø MLS 	14-32275-01 WHT 000 497 A (13x) +WHT 000 789 A (7x) 	

Ⓢ Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / junta para tensor cadena de distribución / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала



15-34088-01 2x 059 198 025 	12-31306-08 2x 036 109 675 (12x) 70-31306-00 24x 036 109 675	71-34082-00 2x 059 129 717 G 	71-34084-00 6x 059 253 039 B 	70-31414-10 	81-24292-10 K ← 054 115 147 B 35x48x10 A SL RD FPM 81-19299-10 K → 068 103 085 E 32x47x10 A SL WD FPM 81-35916-00 K → 070 103 051 A 85x105x12 A SL LD PTFE ACM	
15-34088-01 2x 059 198 025 	12-31306-08 2x 036 109 675 (12x) 70-31306-00 24x 036 109 675	71-34082-00 2x 059 129 717 G 	71-34084-00 6x 059 253 039 B 	70-31414-10 	81-24292-10 K ← 054 115 147 B 35x48x10 A SL RD FPM 81-19299-10 K → 068 103 085 E 32x47x10 A SL WD FPM 81-35916-00 K → 070 103 051 A 85x105x12 A SL LD PTFE ACM	
15-31798-01 2x 078 198 025 	12-31306-10 2x 036 109 675 (15x) 70-31306-00 30x 036 109 675	71-31801-00 2x 078 129 717 J 	71-34047-00 2x 078 253 039 G 	70-31414-10 	81-34366-00 K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM 81-19299-10 N 4x 068 103 085 E 32x47x10 A SL WD FPM	
71-37556-00 03H 103 483 C 	12-31306-05 24x 036 109 675 (24x) 70-31306-00 036 109 675	71-39051-00 03H 133 237 D 	71-39042-00 03H 253 039 H Zyl. 1-3  71-39043-00 03H 253 050 D Zyl. 4-6 	70-31414-10 	81-34819-00 K → 021 103 051 C 85x105x11 A SL LD PTFE ACM	

